

USB422ISO – Converter USB to 2 x RS485 plus 12 VDC power output

Baud Rate of RS422/RS485 port up to 500 kbaud

RS422/RS485 selection by the driver settings and two jumpers

Current on 12 VDC output 0 ... 110 mA

Ripple on 14 VDC output less 100 mVp-p

Switching On 12 VDC by the port initialization

Galvanic isolation of data and power 560 VDC, 420 VAC

Connectors - micro USB and terminal blocks for wire gauge 0,14 - 2,5 mm²

Dimensions 56 x 31 x 25 mm

Drivers for Windows XP, Windows Vista, Windows 7, Windows 8, Windows 10, Mac OS 8, Mac OS 9, Mac OS X, Linux, Windows CE.NET;




Fig. 1. Open lid converter. Connectors




Fig. 2. Cable installation



Fig. 3. Closed lid converter